

# state of Utah DEPARTMENT OF NATURAL RESOURCES Division of Oil, Gas & Mining

MICHAEL R. STYLER **Executive Director** 

JOHN R. BAZA Division Director

## **Inspection Report** Minerals Regulatory Program June 28, 2005

Supervisor

Mine Name: Picture Springs #1 & #2 **Operator Name:** Thirstystone Resources, Inc. Inspector(s): Doug Jensen Other Participants: None

Permit number: S/053/028 Inspection Date: June 22, 2005 Time: 7:00 AM - 7:15 AM

Mine Status: Inactive	Wea	Weather:	
<b>Elements of Inspection</b>	Evaluated	Comment	Enforcement
<ol> <li>Permits, Revisions, Transfer, Bonds</li> <li>Public Safety (shafts, adits, trash, signs, high</li> <li>Protection of Drainages / Erosion Control</li> <li>Deleterious Material</li> <li>Roads (maintenance, surfacing, dust control,</li> <li>Concurrent Reclamation</li> <li>Backfilling/Grading (trenches, pits, roads, highwalls, shafts, drill holes)</li> <li>Water Impoundments</li> <li>Soils</li> <li>Revegetation</li> <li>Air Quality</li> <li>Other</li> </ol>			

## **Purpose of Inspection:**

I stopped by this site while I was in the area.

### **Inspection Summary:**

The site has remained relatively unchanged since my last visit several years ago. A few large rocks have been removed but overall no other changes. The site remains stable with no environmental concerns.

#### Conclusions and Recommendations:

I will continue to monitor this site.

Inspector's Signature

DJ:jb

Thirstystone Resources, Inc., Operator

Rody Cox, BLM, St George FO (UTU-68571)

O:\M053-Washington\S0530028-PictureSpring\inspection\06222005insp.doc